


Existing Conditions

- West Kingtown Train Station**
Issues: Lack of parking; need for covered bike racks
- Ministerial Road**
Issues: Lack of parking, missing side walks, and no sidewalks
- Route 133**
Issues: Missing side walks; no sidewalk
- South Road at Mountain Laurel Drive**
Issue: Signage needed
- Route 102**
Issues: Missing side walks; signage and signals not maintained
- Kerran Road**
Issues: Missing side walks; no crosswalks; stop treated as yield
- Old Tower Hill Road**
Issues: Missing crosswalk and pedestrian light
- Spring Street**
Issue: Poor side walks
- Woodruff Avenue**
Issues: Missing side walk; needs pedestrian light (No photo available)
- High Street**
Issues: Too narrow; needs traffic calming; needs bike path
- Main Street**
Issues: Cars parked blocks to crosswalks; needs mid-street marking/refuge
- Route 1**
Issue: No pedestrian crossings
- Route 1 at Matunuck Exit**
Issue: No pedestrian crossings
- Matunuck Beach Road**
Issue: Needs side walk?
- Matunuck School House Road**
Issues: Needs crosswalk at Matunuck Beach Road; needs signage and markings for bicycles



Potential Solutions

- Bike Amenities:** Bike Lockers, Covered Bike Racks, Wide Shoulder
- Bike Path Amenities:** Lighting, Directional Signage, Designated Parking
- Bike Lanes and Routes:** Striped and Marked Bike Lane, Shared Road Arrows (Sharrows), Curbed Bike Lane, Bike-Friendly Drainage, Protected Shoulder, Highlighted Bike/Car Conflict Points, Bike Route Signage
- Bike Crossings and Intersections:** Highlighted Crossings, Colored Ramps, Crossing Lights and Signage
- Pedestrian Crossings:** Raised Crosswalks, Improved Crosswalk Painting, Textured Crosswalks, Mid-Crossing Signs, Refuge Islands
- Share the Road Signs:** Alert Ramp, Mixed Use Context
- Sidewalks:** Residential Context

Existing Barriers to Walking and Biking

During the South Kingstown Healthy Place by Design project, residents identified areas for improvement. The above map illustrates some barriers to walking and biking in the Town as identified by residents.

What Residents Told Us

Not all potential solutions are appropriate for all barriers or for particular areas in South Kingstown. Improvements must be weighed carefully. In considering potential solutions, decision makers will take into account equal access for all community residents and the need to preserve the rural and historical character of the Town. The potential solutions above are possible changes to remove the barriers to walking and biking.